

Assembly instructions for replacing wheel bearings/hub

Manufacturer:
Volvo

Model: 850, C70, S70, V70 I

LuK AS Part No.:

- 713 6600 40 850
- 713 6603 70 850, V70 I, C70/S70 (→ 12.1998)
- 713 6603 10 C70/ S70/ V70 I (01.1999 →)

OE-No.:
271781
271786
271786-6
272456




Fig. 1

Problem:

Vibrations and or knocking noises after fitting the wheel bearing / hub.

Cause:

The splined drive shaft is loctited into the hub as standard. After re-installation of the splined drive shaft without loctite there may be some play between the hub and the splined drive shaft.

Remedy:

Secure the splined drive shaft with a suitable metal adhesive loctite (e.g. Volvo part number **1161370**) into the hub.

Procedure:

- Clean the spline on the hub and the splined drive shaft.
- Apply a **3-4 mm** bead of the loctite around the outer edge of the straight spline (see **fig. 1**).

Note the specifications of the vehicle manufacturer!

Appropriate spare parts can be found in our on-line catalogue at www.Schaeffler-Aftermarket.com or in RepXpert at www.RepXpert.com.

Issued 11.2007
FAG 0001

Technical subject to change
© 2007 LuK-Aftermarket Service oHG

For further information:

Phone: +44 (0) 14 32 264 264*
Fax: +44 (0) 14 32 275 146
Info@LuK-AS.co.uk
www.Schaeffler-Aftermarket.com
* Calls from within the UK 08457 001100