

# Blue Print Bulletin

## ADC46104C Crank Shaft Pulley

Date Issued: 17/05/2007

### Subject - Product Information

#### Vehicle – Mitsubishi FTO 2.0 (DE3A)

We have been made aware that the Crankshaft pulley fitted on the Import Mitsubishi FTO 2.0 model is prone to partial or full failure during its service life.

The Crankshaft pulley consists of two sections (Inner and outer), which are connected by a rubber damper.

This can in time slowly break up causing movement on the pulley.



ADC46104C

If the Crankshaft pulley is operating with a worn rubber damper at high engine RPM, the pulley can oscillate and in extreme cases there is a possibility that the outer part of the pulley can come adrift.

This excessive movement can cause the timing belt cover to move inwards and damage the Crank Angle Sensor Blade. If this part is damaged, the blade will act like a "knife" against the timing belt, with the potential of causing catastrophic engine failure

#### Linked part number: Crank Angle Sensor = ADC47201

Applications:

- Mitsubishi FTO & Legnum
- Mitsubishi Galant



ADC47201

**Disclaimer :** Any technical tips are produced in good faith. Automotive Distributors Ltd. always recommend that vehicle maintenance and diagnostics are only carried out by suitably experienced people using appropriate tools in a safe manner within a workshop environment. Automotive Distributors Ltd. and their customers cannot be held responsible for the correctness of, or misinterpretation of the above technical tips. Images shown are for illustrative purposes only and may not be representative of the products or vehicles described.

**Technical Helpline: +44 (0)1622 833004 Fax: +44(0)1622 834004**

