



# VKJA 5756

## Technical Bulletin – December 2010

VKJA 5756



Renault



Technical Information: VKJA 5756 Replacement guidelines



This bulletin describes the replacement guidelines of a wheel side CVjoint on a Renault LAGUNA Grandtour (K56\_) 2.0 (K56C/H).

CAR MAKER	MODEL	ENGINE
RENAULT	LAGUNA (B56_, 556_)	1.8 (B56A/B)
RENAULT	LAGUNA (B56_, 556_)	2.0 (B56C/H/N)
RENAULT	LAGUNA (B56_, 556_)	1.8 (B56S/T/O)
RENAULT	LAGUNA Grandtour (K56_)	1.8 (K56S/T/O)
RENAULT	LAGUNA Grandtour (K56_)	1.8 (K56Z)
RENAULT	LAGUNA Grandtour (K56_)	2.0 (K56C/H)

Time for replacement	
CV-Joint VKJA 5756	Left wheel: 2 h 15 min Right wheel: 2 h 25 min



Always follow workshop health & safety procedures when carrying out repairs.



## VKJA 5756: Removal of the CV-Joint

1. Remove the driveshaft in accordance with the vehicle manufactures' workshop manual.



2. Place the driveshaft in a vice (with aluminum or protective jaws).

Remove both the inner and the outer clips.  
Cut the boot and remove it.

3. Hold the CV-Joint and pull it off the shaft by tapping with a hammer



4. Expand and remove the circlip with circlip removal pliers.

## VKJA 5756: Installation of the new CV-Joint



1. Put the short boot clamp on the shaft.  
Slide the boot on the shaft.

2. Fix the new circlip into the groove.  
Tip: To keep it into the groove use a hose clip (do not over tighten!)



3. Press the new CV-joint onto the shaft.  
Tap with a rubber hammer until the circlip locks into its groove in the inner race of the CV-joint.  
Remove the hose clip.

4. Slide the boot into position ready for mounting and fill with all of the supplied grease.



5. Fit the short clamp onto the CV-boot and tighten it with a suitable tool.  
Pull the boot onto the CV-joint.

6. Fit the long clamp and tighten it with the same tool.



© SKF is a registered trademark of the SKF Group.

© SKF Group 2011

The contents of this publication are the copyright of the publisher and may not be reproduced (even extracts) unless written permission is granted. Every care has been taken to ensure the accuracy of the information contained in this publication but no liability can be accepted for any loss or damage whether direct, indirect or consequential arising out of the use of the information contained herein.

