

T43090

VAG 1.0 16V AST / AVZ & 1.4 16V AFH




Fig. 1

The tensioner pulley has a "ridged" surface (Fig. 1 and 2).

This is intentional. These "ridges" are designed to help reduce belt noise generated by surface contact.



Fig. 2

When replacing the timing belt, ensure that a new "ridged" tensioner is installed at the same time.