

Design change affecting tensioning pulley 531 0203 20

Vehicle manufacturer:	Audi, Seat, Skoda, Volkswagen
Models:	
Audi:	A3, A4
Seat:	Alhambra, Altea, Altea XL, Cordoba, Ibiza III, Leon, Toledo II, Toledo III
Skoda:	Fabia, Octavia, Superb
VW:	Bora, Caddy III, Golf IV, Golf V, Golf VI, Jetta III, New Beetle, Passat, Polo, Sharan, Touran, Multivan/Transporter T5
Engines:	1.6, 2.0, 2.0i
OE-Nos.:	06A 109 479 (replaced) 06A 109 479 A (replaced) 06A 109 479 B (replaced) 06A 109 479 C (replaced) 06A 109 479 F (current)
Item no.:	531 0203 20



Image 1: 531 0203 20 – previous design




Image 2: 531 0203 20 - new design

Due to the constant development of our products, the design of tensioning pulley 531 0203 20 has been changed. This Service Information sheet shows the visible differences between the two versions from the front and back of each tensioning pulley.

We may have mixed stocks during the transitional phase. Both tensioning pulleys meet the technical specifications and can be used without restrictions on the specified vehicles.

Note:

The special tool (OE no. T10020) for turning the eccentric is no longer needed. Please use a 6 mm allen key.



Note the specifications of the vehicle manufacturer!

Appropriate spare parts can be found in our on-line catalogue at www.Schaeffler-Aftermarket.com or in RepXpert at www.RepXpert.com.

Issued 12.2009

INA 0049

Technical subject to change

© 2009 Schaeffler Automotive Aftermarket oHG

For further information:

Phone: +44 (0) 14 32 264 264*

Fax: +44 (0) 14 32 375 760

Info@LuK-AS.co.uk

www.Schaeffler-Aftermarket.com

* Calls from within the UK 08457 001100

