



## Service Info



# Pulse sensor 544 0095 10

## Damage during removal

Manufacturer: Citroën, Fiat, Ford, Jaguar, Peugeot

**Models:**

Citroën : C4, C5, C8  
 Fiat: Scudo  
 Ford: Grand C-Max, Mondeo  
 Jaguar: XF  
 Peugeot: 508, 807

**Engines:** 2.0 Diesel, 2.2 Diesel

**Part no.:** 544 0095 10

For current listing refer to parts catalogue



The pulse sensor for the engine management system (Fig 1.) is made of different material to the crankshaft vibration damper which may lead to corrosion between the parts.

Fig. 1: 544 0095 10 – Pulse sensor for engine management

Because of this in most cases the part is damaged during removal and should therefore be replaced each time it is removed.

During installation of the crankshaft vibration damper, the specified tightening torque of the vehicle manufacturer must be observed.



Fig. 2: Pulse sensor and crankshaft vibration damper

Please observe the vehicle manufacturer specifications!

**You want more? We can help!**

Phone: +44 (0) 1432 264 264\*  
 Fax: +44 (0) 1432 375 760  
 hfd-info@schaeffler.com  
 www.schaeffler-aftermarket.co.uk

\* Calls from within the UK 08457 001100

Issued 11.2015 INA 0148 Technical content subject to change  
 O.E. Manufacturer's names and numbers are used for reference purposes only  
 © 2015 Schaeffler Automotive Aftermarket GmbH & Co. KG

