


de Innenraumfilter
en Cabin filter
fr Filtre d'habitacle
it Filtro abitacolo
es Filtro ventilacion para interior
pt Filtro de purificação do habitáculo
sv Kupéfilter
nl Interieurfilter

1 987 433 E71









BOSCH





1 987 432 223

Chevrolet Lancetti	❄	03.05 →
Chevrolet Nubira	❄	01.05 →
Daewoo Lancetti	❄	02.04 →
Daewoo Nubira	❄	07.03 →







Service
+49 (0) 180-500 4745




gebührenpflichtig/subject to charges/payant

Robert Bosch GmbH

Postfach 41 09 60, D-76225 Karlsruhe

www.bosch-automotive.com



Gedruckt auf Recycling-Papier Printed in Germany

Printed on recycled paper Imprimé en Allemagne