

## Optimized tensioning pulley 531 0564 30

### Manufacturer:

Seat, Volkswagen

### Model:

- Seat Polo
- Volkswagen Cordoba, Ibiza


### Engine:

1.4i 16V (AFH)


**LuK AS Part No.:** 531 0564 30

### OE-No.:

036 109 243 J  
036 109 243 G (replaced)  
036 109 243 D (replaced)



**Fig. 1:** 531 0564 30 (front view)



**Fig. 2:** 531 0564 30 (side view)

Tensioning pulley **531 0564 30** (sinus pulley) is a noise-optimized tensioning pulley, developed specially for the applications outlined above.

The red markings (**fig. 1** and **fig. 2**, arrows) highlight the features.

The running surface of the tensioning pulley has diagonal elevations (**fig. 2**).

### Note:

The unusually formed running surface is **not** a production fault!

Appropriate spare parts can be found in our on-line catalogue at [www.Schaeffler-Aftermarket.com](http://www.Schaeffler-Aftermarket.com) or at [www.RepXpert.com](http://www.RepXpert.com).

Issued 11.2007

**INA 0009**

Technical subject to change

© 2007 LuK-Aftermarket Service oHG

### For further information:

Phone: +44 (0) 14 32 264 264\*

Fax: +44 (0) 14 32 275 146

Info@LuK-AS.co.uk

[www.Schaeffler-Aftermarket.com](http://www.Schaeffler-Aftermarket.com)

\* Calls from within the UK 08457 001100

