



## Service Info



# Over-running alternator pulley 535 0210 10

## Visual differences

Manufacturers: Audi, Seat, Volkswagen

### Models:

Audi: A4, A5, A6, Q3, Q5

Seat: Exeo

Volkswagen: Amarok, T5

Engines: 1.8, 2.0 TSI, 2.0 TFSI

Part no.: 535 0210 10



Image 1: version 1



Image 2: version 2

Version 1 (image 1) or version 2 (image 2) of an over-running alternator pulley can be installed on the Alternators of the aforementioned vehicles.

Both versions differ only in their appearance. They both meet the technical specifications and can be used without restrictions in the specified vehicles.

For this reason, Schaeffler Automotive Aftermarket only offers the over-running alternator pulley 535 0210 10 in version 1 (image 1).

Observe the specifications of the vehicle manufacturer!

Spare parts and technical information can be found under [www.schaeffler-aftermarket.com](http://www.schaeffler-aftermarket.com) or [www.RepXpert.com](http://www.RepXpert.com).

Phone: +44 (0) 14 32 264 264\*  
 Fax: +44 (0) 14 32 375 760  
[hfd-info@schaeffler.com](mailto:hfd-info@schaeffler.com)  
[www.schaeffler-aftermarket.com](http://www.schaeffler-aftermarket.com)

\* Calls from within the UK 08457 001100

**SCHAEFFLER**  
 AUTOMOTIVE AFTERMARKET

