

# Blue Print Bulletin

## PT Cruiser Thermostat Housing - ADA109212

Date Issued: 01/3/2011

### Key Points

- Highly requested **common failure part**
- Covered by the standard Blue Print **3 Year Warranty**
- Over **16,000** applicable vehicles on the UK's roads

### ADA109212

#### Thermostat Housing

Chrysler PT Cruiser 2.0i, 2.4i 2000>



The thermostat housing/coolant filler neck is a plastic moulded item (located towards the OSF of the engine compartment) that can often warp or crack from thermal expansion and contraction.

Replacement is the only option for a long-lasting repair, and it is considered good practice to renew the thermostat and gasket (**ADA109210C**) at the same time as there would be no additional labour involved.

No specialist tools are required for changing the thermostat or housing.

Unlike the main dealer, Blue Print offers a 3 Year unlimited mileage warranty on every part, meaning peace of mind for the vehicle owner knowing that they won't need to pay for the same repair anytime soon.

The Thermostat Housing is also referred to as -

- Filler Neck and Thermostat Housing
- Thermostat Housing Cover

Also available...

### ADA109210C

#### Thermostat

Chrysler PT Cruiser 2.0i, 2.4i 2000>



**Disclaimer:** Any technical tips are produced in good faith. Automotive Distributors Ltd. always recommend that vehicle maintenance and diagnostics are only carried out by suitably experienced people using appropriate tools in a safe manner within a workshop environment. Automotive Distributors Ltd. and their customers cannot be held responsible for the correctness of, or misinterpretation of the above technical tips. Images shown are for illustrative purposes only and may not be representative of the products or vehicles described.

Technical Helpline: +44 (0)1622 833004 Fax: +44(0)1622 834004

