

Conductor Plate Kit for automatic transmissions

febi no. 39942

Repl. no. 521 083 08 AB S1

Fits all Chrysler 5-gear automatic transmissions.

The sensors of the conductor plate stick together due to deposits in the automatic transmission fluid. This results in gear change malfunctions in the transmission.



Please note!


Always replace the plug at the same time as replacing the conductor plate. Otherwise leaks may occur at the outlet from the conductor plate. As a result the oil perforates the seal and can therefore get into the automatic transmission control unit via the wiring loom and lead to damage in the control unit.

For this reason, febi bilstein supplies the complete kit febi 39942 which includes both the conductor plate febi 39482 and also the plug for automatic transmissions febi 36332. This combination enables a professional repair and avoids potential complaints. That saves time and money for both workshop and customer!



febi no. 39942

febi no. 39482



febi no. 36332



febi bilstein also supplies the conductor plate and plug separately.

Simply ask for spare parts by febi bilstein.

The complete range can be found at: www.febi-parts.com

Register now at www.febi.com for the official newsletter of febi bilstein and get the latest technical information automatically by email!

Subject to technical changes