

NEW PRODUCT HIGHLIGHT | JAN2020



febi 103487

to fit:
Renault Trucks C-, K-, T- Serie,
Kerax, Magnum, Premium
Volvo Trucks FH/FM, FMX, NH1



EN

WATER SEPARATOR FOR FUEL SYSTEM

Function

A diesel engine cannot function when there is water present in the fuel. In the worst case scenario, components of the injection system can suffer irreversible damage. To prevent this, water separators are installed in the fuel system.

The water separator febi 103487 is located on the underside of the fuel filter. If water collects there, the driver is informed via a display. The water can then be drained from the water separator by means of a solenoid valve.

Cause of Failure

Since the water separator is equipped with a sensor and a solenoid valve, electrical contact problems are often the cause of failure. If the water separator is additionally equipped with a fuel heater, the risk of electrical faults is even higher. In most cases, a repair is not reasonable, therefore making it necessary to replace the water separator.

For more technical information please visit: partsfinder.bilsteingroup.com