

Manufacturers part numbers are quoted for reference only

**Type** **Baumuster**

4.326.310 ▶CHno  
(BM 381.082, 182)

381.082  
381.182  
383.146



**1419 AK**  
WB 3200











**1219 F**  
WB 3200  
**1219 AF**  
WB 3200











**Front pipe**

**Silencer**

**Tail pipe**

<p><b>50165</b> 385.490.0119</p> <p>Right hand side</p> 	<p><b>50167</b> 383.492.0007</p> 	<p><b>50171</b> 383.492.0701</p> 	<p><b>50315</b> 383.490.0301</p> 	<p><b>50641</b> 381.492.6304</p> 
<p><b>50166</b> 385.490.0219 385.490.0019</p> <p>Left hand side</p> 	<p><b>50167</b> 383.492.0007</p> 	<p><b>50169</b> 383.492.0601</p> 		

**Mounting Parts**

<p>1. <b>50864</b> 383.492.0140</p> 	<p>2. <b>50888</b> 383.490.0040</p> 	<p>3. <b>50809</b> 381.492.0082 301.492.0382 0201.175.00</p> 	<p>4. <b>50881</b> 381.491.0416</p> 	<p>5. <b>50822</b> 617.492.2841 383.492.1341 617.492.1341</p> 
<p>6. <b>99765</b> 071.555.065.501</p> 	<p>7. <b>50903</b> 302.490.0080 442.492.0080</p> 	<p>8. <b>50861</b> 381.492.1941</p> 	<p>9. <b>50910</b> 384.987.7140 001.987.9640 001.987.5340</p> 	<p>10. <b>99775</b> 071.555.075.502</p> 

Horizontal  
LHD  
Standard