

Product info sheet

Robert Bosch

0445110029

Special tools needed?

No

Product specific information

Programming

No

Unlocking

No

Adaption values reset

No

Bleed

No

adjustment at mounting_1

--

adjustment at mounting_2

Tightening torques

Injector/ retaining clamp

10 Nm (2 pieces tighten equally)

High Pressure pipe nuts

30 Nm

Inlet manifold

M6: 10 Nm, M7: 15 Nm, M8: 22 Nm

Assembly instructions

Replace sealing washer

Recommendation: replace gasket inlet manifold

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.

