

Product info sheet

Robert Bosch

0445110049

Special tools needed?

No

Product specific information

Programming

No

Classification code

All new and overhauled injectors will be considered as class C0.

Unlocking

No

Adaption values reset

No

Bleed

No

adjustment at mounting_1

--

adjustment at mounting_2

Tightening torques

Injector/ retaining clamp

10 Nm (2 pieces tighten equally)

High Pressure pipe nuts

30 Nm

Inlet manifold

M6: 10 Nm, M7: 15 Nm, M8: 22 Nm

Assembly instructions

Replace sealing washer

Recommendation: replace gasket inlet manifold

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.

