

-no heavy corrosion.

<b>Product info sh</b>	neet	Robert Bosch	0445110087
Special tools needed?	No		
	Pro	oduct specific inform	ation
Programming	No		
10000			
Unlocking	No		
Adaption values reset	No		
Bleed	No		
adjustment at mounting_1			
			=
adjustment at mounting_2			
		Tightening torque	c
Injector/ retainingclamp			es: 6 Nm 2: Flywheelside: +360°
High Pressure pipe nuts		27 Nm	,
		A   -	
		Assembly instructio	ins
Replace bolts/studs and nu	ıts		
Replace sealing washer			
Core charge terms:			
-externally intact,			
-no mechanical damage,			
-not dismantled,			