

Product info sheet

Robert Bosch

0445110216

Special tools needed?

No

Product specific information

Programming

Yes

IMA code (7 characters)

Unlocking

No

Adaption values reset

No


Bleed

No

adjustment at mounting_1

--

adjustment at mounting_2



Tightening torques

Injector/ retaining clamp

9 Nm (tighten 2 pieces evenly)

High Pressure pipe nuts

23 Nm

Inlet manifold

M6: 10 Nm, M7: 15 Nm, M8: 22 Nm

Assembly instructions

Replace sealing washer

Recommendation: replace gasket inlet manifold

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.

