

## Product info sheet

Robert Bosch

0445110219

Special tools needed?

No

## Product specific information

Programming

Yes

IMA code (7 characters)

Unlocking

No

Adaption values reset

No


Bleed

No

adjustment at mounting\_1

--

adjustment at mounting\_2



## Tightening torques

Injector/ retaining clamp

9 Nm (tighten 2 pieces evenly)

High Pressure pipe nuts

23 Nm

Inlet manifold

M6: 10 Nm, M7: 15 Nm, M8: 22 Nm

## Assembly instructions

Replace sealing washer

Recommendation: replace gasket inlet manifold

### Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.

