

Product info sh	neet	Robert Bosch	0445110276
Special tools needed?	No		
		duct specific informa	tion
Programming	Yes	IMA code (9 characters)	KXXX
Unlocking	No		
Adaption values reset Bleed	No		
adjustment at mounting_1			
dajastificite at modificing_1	-		
adjustment at mounting_2	2		
		Tightoning torques	
lui actou / notai nin aclanan		Tightening torques 32 Nm	
Injector/ retainingclamp High Pressure pipe nuts		29 Nm	
riigii i ressure pipe nats		25 11111	
			Allering
		Assembly instruction	S
Replace sealing washer			
Core charge terms:			
-externally intact,			
-no mechanical damage,			
-not dismantled, -no heavy corrosion.			
TIO HEAVY COLLOSIOH.			