

-no mechanical damage,

-not dismantled,-no heavy corrosion.

Product info sh	eet	Robert B	osch	0445110298
Special tools needed?	No			
	Pro	oduct specifi	c informatior	1
Programming	Yes	IMA code (8 cha		
Unlocking	No			
Adaption values reset	No			8-stelling
Bleed	Yes	Help with manu	ual pump before fuel	filter
adjustment at mounting_1	No			
adjustment at mounting_2				
		Tightoning	torques	
Injector/ retainingclamp		Tightening	•	
injector/ retainingcramp		131	VIII	
				Access to the second
		Assembly in	structions	
Replace sealing washer Recommendation: replace fuel filter				
Core charge terms:				
-externally intact,				