

| Product info sheet | | Robert Bosch | | 0445110569 |
|---|--------|--------------|-----------------|--|
| Special tools needed? | No | | | |
| Product specific information | | | | |
| Programming Unlocking | Yes IN | ЛА code (7 (| characters) | 178 (178) (1 |
| Adaption values reset | | eset adaptiv | ve values | THU TEST |
| Bleed | Yes | se manual բ | oump on vehicle | |
| adjustment at mounting_1 adjustment at mounting_2 | No | | | |
| Tightening torques | | | | |
| Injector/ retainingclamp | | 3 | 5 Nm | /////////////////////////////////////// |
| High Pressure pipe nuts | | | 2 Nm | |
| Assembly instructions | | | | |

Core charge terms:

- -externally intact,
- -no mechanical damage,

Replace sealing washer

Replace tension bolts

- -not dismantled,
- -no heavy corrosion.







Recommendation: replace fuel filter