


Product info sheet

Robert Bosch

0445110616

Special tools needed?

No



Product specific information

Programming

Yes

IMA code (7 characters)

Unlocking

No

Adaption values reset

No

Bleed

Yes

ignition on for 30 seconds

adjustment at mounting_1

No

adjustment at mounting_2

No

Tightening torques

Injector/ retaining clamp

1: 8 Nm, 2: 26 Nm

High Pressure pipe nuts

24 Nm

Assembly instructions

Replace sealing washer

Recommendation: replace fuel filter

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.

