

DIESEL BUCHLI


Robert Bosch 0445110634

Special tools needed?

Product info sheet

Yes


Injectors can be very stuck. Please contact us if you don't have the right equipment.



Stanadyne YANMAR

Product specific information

IMA code (7 characters) Yes Programming No Unlocking No Adaption values reset Bleed No



adjustment at mounting_2

adjustment at mounting_1 No

Tightening torques

Injector/ retainingclamp High Pressure pipe nuts

35 Nm 32 Nm

Assembly instructions

Replace sealing washer

Recommendation: replace fuel filter Recommendation: replace sealing ring

Core charge terms:

- -externally intact,
- -no mechanical damage,
- -not dismantled,
- -no heavy corrosion.





