

Product info sheet

VDO

A2C59507596

Special tools needed?

No

Product specific information

Programming

Yes

Calibration code (6 characters)

Unlocking

No

Adaption values reset

No

Bleed

Yes

ignition on for 30 seconds

adjustment at mounting_1

No

adjustment at mounting_2



Tightening torques

Injector/ retainingclamp

30 Nm

Assembly instructions

Replace sealing washer

Replace tension bolts

Recommendation: replace fuel filter

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.