

Product info sheet

VDO

GK2Q9K546AC

Special tools needed?

No

Product specific information

Programming

Yes

Calibration code

Unlocking

No

Adaption values reset

No

Bleed

No

adjustment at mounting_1

No

adjustment at mounting_2



Tightening torques

Injector/ retaining clamp

1: 6 Nm 2: 45°, Loosen, 3: 6 Nm 4: 135°

Assembly instructions

Replace sealing washer

Replace tension bolts

Recommendation: replace fuel filter

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.