


de Innenraumfilter
en Cabin filter
fr Filtre d'habitable
it Filtro abitacolo
es Filtro ventilacion para interior
pt Filtro de purificação do habitáculo
sv Kupéfilter
nl Interieurfilter

1 987 431 E85






BOSCH







1 987 432 043 / 1 987 432 343

VW LT 05.96 → 07.06

Mercedes-Benz
Sprinter 02.95 → 05.06







Service
+49 (0) 180-500 4745



gebührenpflichtig/subject to charges/payant

Robert Bosch GmbH

Postfach 41 09 60, D-76225 Karlsruhe

www.bosch-automotive.com



Gedruckt auf Recycling-Papier Printed in Germany

Printed on recycled paper Imprimé en Allemagne