

SERVICE INFO



Change to the pulleys of a few tensioning arms for the accessory unit drive

Vehicle

Manufacturers: Audi, Chevrolet, Isuzu, Land Rover, MG, Opel, Renault, Rover, Seat, Skoda, Vauxhall, Volkswagen, Volvo

Part Nos.:

533 0077 30
534 0082 30
534 0083 30
534 0133 30
534 0136 30
534 0139 30

You can find the extensive vehicle classifications in our catalogue.




Image 1: Detailed view of pulley in its previous design (left) and new design (right)

From now on, Schaeffler Automotive Aftermarket will offer versions with a modified pulley for the listed tensioning arms.

The differences are, as are shown in Image 1, the coating (previously black, now metal) and the connection between both race halves (previously riveted, now tox clinched).

During the transition period, we may have mixed stocks of both designs. Both versions meet the technical specifications and can be used without restrictions on the vehicles specified in the catalogue.



Note the specifications of the vehicle manufacturer!

Appropriate spare parts can be found in our on-line catalogue at www.Schaeffler-Aftermarket.com or in RepXpert at www.RepXpert.com.

Issued 03.2010

INA 0055

Subject to technical changes

© 2010 Schaeffler Automotive Aftermarket

For further information:

Phone: +44 (0) 14 32 264 264*

Fax: +44 (0) 14 32 375 760

Info@LuK-AS.co.uk

www.Schaeffler-Aftermarket.com

* Calls from within the UK 08457 001100

