



Service Info



Belt tensioner 534 0111 20

Visual differences

Manufacturers: Citroën, Fiat, Peugeot, Suzuki

Models:

Citroën: Berlingo, C4, Jumper, Jumpy, Xsara

Fiat: Ducato, Scudo

Peugeot: 206, 306, 307, Boxer, Expert, Partner

Suzuki: Vitara

Engines: 1.9 D, 2.0 HDI, 2.0 JTD

Part no.:
529 0019 10
529 0107 10
534 0111 20



Figure 1: Previous design



Figure 2: New design

As part of our continuous efforts to improve our products, modifications have been made to the belt tensioner with part number 534 0111 20.

This Service Information sheet shows the visual features of the previous version (Figure 1) and the new version (Figure 2).

During the transition period, we may have mixed stocks of both types.

The two versions differ only in their appearance. Both comply with the technical specifications and can be used without restrictions.

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264*

Fax: +44 (0) 1432 375 760

hfd-info@schaeffler.com

www.schaeffler-aftermarket.co.uk

* Calls from within the UK 08457 001100

