


Montageanleitung | Installation Instruction | Notice de montage
Istruzioni di montaggio | Instrucciones de montaje
Instruções de montagem | Installationsanvisning | Montagehandleiding

de Innenraumfilter
en Cabin filter
fr Filtre d'habitacle
it Filtro abitacolo
es Filtro ventilacion para interior
pt Filtro de purificação do habitáculo
sv Kupéfilter
nl Interieurfilter

1 987 433 E72






BOSCH









1 987 432 224



Hyundai ix35
Hyundai Tucson

04.10 ->
08.04 ->











Service

+49 (0) 180-500 4745



gebührenpflichtig/subject to charges/payant

Robert Bosch GmbH

Postfach 41 09 60, D-76225 Karlsruhe

www.bosch-automotive.com



Gedruckt auf Recycling-Papier Printed in Germany

Printed on recycled paper Imprimé en Allemagne