



Manufacturers part numbers are quoted for reference only

Type

 
5 cyl. D2865 turbo

16/19 ton

F01
1985 →
F

F02
1985 →
FL

F03
1986 →
FLL

26 ton


F18
13/91 → 01/92
FNL

Front pipe

Silencer


Tail pipe

49166
81.15204.5460




49169
81.15204.5461


Ref.no. 81.15000.7347
F01, F02, F18




49133
81.15210.0054




49131
81.15204.0094



49324
81.15101.0223
81.15101.0207
81.15101.0247
Ref.no. 020-314, 315, TUV,
KBA no. 21199,
Standard/special




49658
81.15204.0230
81.15204.0198




49180
81.15204.5635

Ref.no. 81.15000.7459
F01, F02, F18




49132
81.15204.0052




49171
81.15204.5462

Ref.no. 81.15000.7348
F03




49190
81.15204.5648

Ref.no. 206-636
→ 03/92
With retarder




Mounting Parts


1.
99714
81.97420.0085
88.15640.2203
81.97420.0152



3.
99710
88.15640.0000
81.97420.0073



4.
49910
81.96210.0153
81.96210.0127
81.96210.0602



5.
49905
81.97460.5245



6.
49825
81.15501.5536
81.15501.5516



7. Excl. 
49826
81.15110.0250
81.15110.0205





8.
49814
81.15110.0175





9.
49821
81.97460.6021



3.




7.




Horizontal
LHD
Left