

Manufacturers part numbers are quoted for reference only

**Type**

 FNLL  
5 cyl. D2865 turbo


**F06**  
22/24/25/26 ton  
28/86 → 01/94

**Front pipe**

**Silencer**

**Tail pipe**

**49167**  
81.15204.5478

Ref.no. 280-373, 374, 375,  
6 Cyl. D2866 LF, LXF, turbo, intercooler,  





**49212**  
81.15204.5480




**49133**  
81.15210.0054



**49131**  
81.15204.0094



**49324**  
81.15101.0223  
81.15101.0207  
81.15101.0247  
Ref.no. 81.15000.7324, ref.no.  
020-154, 155, 168, 206-532, 553, 591,  
592



**49658**  
81.15204.0230  
81.15204.0198



**49166**  
81.15204.5460

5 Cyl. D2865 engine




**49171**  
81.15204.5462  
  
Ref.no.  
81.15000.7348



**49132**  
81.15204.0052

Ref.no.  
81.15000.7324,  
ref.nr. 206-609  
24/91 →  
With retarder



N.A.

81.15101.0225  
81.15101.0226  
81.15101.0248

N.A.  
  
81.15204.0032











**49136**  
81.15204.5421



**49137**  
81.15204.5420  
  
L=60



**Mounting Parts**

- |  |   |   |  |  |
|--|---|---|--|--|
| 1.<br><b>99714</b><br>81.97420.0085<br>88.15640.2203<br>81.97420.0152<br> | 2.<br><b>49904</b><br>81.15901.0010<br>  | 3.<br><b>99710</b><br>88.15640.0000<br>81.97420.0073<br> | 4.<br><b>49910</b><br>81.96210.0153<br>81.96210.0127<br>81.96210.0602<br> | 5.<br><b>49905</b><br>81.97460.5245<br> |
| 6.<br><b>49825</b><br>81.15501.5536<br>81.15501.5516<br>                  | 7. Excl. <br><b>49826</b><br>81.15110.0250<br>81.15110.0205<br> | 8.<br><b>49814</b><br>81.15110.0175<br>                  | 9.<br><b>49821</b><br>81.97460.6021<br>                                   |  |

Horizontal  
LHD  
Left