


Manufacturers part numbers are quoted for reference only

**Type** **Baumuster**


►CHno 4.827.814

 **2528**  
WB 4100  
**1928 A**  
WB 4100, 4500  
**1935 A**  
WB 4500  
**1936 A**  
WB 4500  
**2428 A**  
WB 4100  
**2528 A**  
WB 4100










621.214  
621.215  
621.312  
621.316  
621.317

 **1928 AS**  
WB 3500

 **1928 AK**  
WB 3500, 3800  
**2528 AK**  
WB 3500, 3800



**Mounting Parts**

- |   |   |   |   |  |  |  |   |   |
|---|---|---|---|--|--|--|---|---|
| <p>1.</p> <p><b>50813</b><br/>655.490.0942<br/>621.490.0042</p>  | <p>2.</p> <p><b>99778</b><br/>071.555.078.502</p>  | <p>3.</p> <p><b>99775</b><br/>071.555.075.502</p>  | <p>4.</p> <p><b>50903</b><br/>302.490.0080<br/>442.492.0080</p>  | <p>5.</p> <p><b>51807</b><br/>387.492.0240</p>  | <p>6.</p> <p><b>50803</b><br/>000.142.3957</p>  | <p>7.</p> <p><b>50822</b><br/>617.492.2841<br/>383.492.1341<br/>617.492.1341</p>  | <p>8.</p> <p><b>50809</b><br/>381.492.0082<br/>301.492.0382<br/>0201.175.00</p>  | <p>9.</p> <p><b>50817</b><br/>621.492.0441<br/>621.492.0341</p>  |
|---|---|---|---|--|--|--|---|---|

Horizontal  
LHD  
Standard