


Manufacturers part numbers are quoted for reference only

Type

 **1922**
WB 3800

 **1922 K**
WB 3500, 3800












Baumuster

656.106
656.107









Front pipe

Silencer

Tail pipe

<p>N.A.</p> <p>655.490.0725</p> 	<p>50277 620.490.0465</p> 	<p>51170 620.492.0208</p> 	<p>52213 655.490.0319</p> 	<p>50420 645.490.0601</p> 	<p>N.A.</p> <p>655.492.0314 655.492.2004</p>
<p>52210 655.490.0625</p> <p>Left hand side</p> 	<p>50277 620.490.0465</p> 	<p>51170 620.492.0208</p> 	<p>52212 655.490.0219</p> 	<p>50420 645.490.0601</p> 	<p>52721 655.492.0514 655.492.1904</p> 

Mounting Parts

<p>1.</p> <p>50903 302.490.0080 442.492.0080</p> 	<p>2.</p> <p>50852 620.997.0590</p> 	<p>3.</p> <p>50917 674.492.0340 620.492.0940</p> 	<p>4.</p> <p>99794 071.555.094.502</p> 	<p>5.</p> <p>99775 071.555.075.502</p> 	<p>6.</p> <p>50822 617.492.2841 383.492.1341 617.492.1341</p> 	<p>7.</p> <p>50809 381.492.0082 301.492.0382 0201.175.00</p> 	<p>8.</p> <p>50817 621.492.0441 621.492.0341</p> 
---	--	--	---	---	--	---	---

Horizontal
LHD
Standard