


Manufacturers part numbers are quoted for reference only

**Type** **Baumuster**

5.193.595 ▶CHno  
  
**1922**  
 WB 4500, 4800,  
 5500, 5900  
**2222**  
 WB 4800  
**2422**  
 WB 4500, 4800,  
 5500, 5900  
**2622**  
 WB 4800

621.005  
 621.006  
 621.007  
 621.008


**Front pipe**

**51213**  
 621.490.0725


Right hand side



**50217**  
 620.490.0365




**50218**  
 617.492.0008  
 620.492.0008




**N.A.**  
 624.490.2419

**51212**  
 621.490.0625


Left hand side



**50217**  
 620.490.0365



**50218**  
 617.492.0008  
 620.492.0008



**51208**  
 624.490.2319



**Silencer**

**50364**  
 617.490.1901




**Tail pipe**

**N.A.**  
 624.492.2204

**Mounting Parts**

1.  
**50810**  
 620.997.0490



2.  
**50827**  
 620.492.0840  
 620.490.0840




3.  
**99778**  
 071.555.078.502



4.  
**50903**  
 302.490.0080  
 442.492.0080



6.  
**50807**  
 620.491.0321  
 620.490.0441



Horizontal  
 LHD  
 Standard