

Manufacturers part numbers are quoted for reference only

**Type** **Baumuster**

5.129.245 ▶CHno  
5.165.436










622.570

  
© X 0/0  
**2033 LS**  
WB 2400











**Front pipe**

**Silencer**

**Tail pipe**

<p><b>51197</b> 620.490.2525</p> <p>Right hand side</p> 	<p><b>50277</b> 620.490.0465</p> 	<p><b>51170</b> 620.492.0208</p> 	<p>N.A.</p> <p>622.490.0919</p>	<p><b>50357</b> 624.490.4201 622.490.0101</p> 	<p><b>51655</b> 622.492.0204</p> <p>Right hand side</p> 
<p>N.A.</p> <p>622.490.0525 Left hand side</p>	<p><b>50277</b> 620.490.0465</p> 	<p><b>51170</b> 620.492.0208</p> 	<p>N.A.</p> <p>622.490.0819</p>	<p><b>50357</b> 624.490.4201 622.490.0101</p> 	<p><b>51656</b> 622.492.0104</p> <p>Left hand side</p> 

**Mounting Parts**

<p>1. <b>50852</b> 620.997.0590</p> 	<p>2. <b>50813</b> 655.490.0942 621.490.0042</p> 	<p>3. <b>99794</b> 071.555.094.502</p> 	<p>4. <b>99775</b> 071.555.075.502</p> 	<p>5. <b>50809</b> 381.492.0082 301.492.0382 0201.175.00</p> 	<p>6. <b>50913</b> 0201.178.00 350.492.0080 0201.141.00</p> 	<p>7. <b>50917</b> 674.492.0340 620.492.0940</p> 	<p>8. <b>51820</b> 622.492.0040</p> 	<p>9. <b>51835</b> 619.492.0241 617.492.0141</p> 	<p>10. <b>51836</b> 620.491.0141</p> 
---	--	--	--	--	---	--	---	--	--

Horizontal  
RHD  
Standard