

-no heavy corrosion.

<b>Product info s</b>	heet	Robert Bosch	0445110102	
Special tools needed?	No			
	Pro	oduct specific informa	ation	
Programming	No			
Unlocking	No			
Adaption values reset	No			
Bleed	No			
adjustment at mounting	_1			
1	2	1		
adjustment at mounting				
		Tightening torques		
Injector/ retainingclamp			1: Nuts both sides: 6 Nm 2: Flywheelside: +360°	
High Pressure pipe nuts		27 Nm		
			Account of the form	
		Assembly instruction	ns	
Replace bolts/studs and	nuts	,,		
Replace sealing washer	iidts			
0				
		N.C.		
Core charge terms:				
-externally intact, -no mechanical damage	2.			
-not dismantled,	-,			