

Product info sheet

Robert Bosch

0445110252

Special tools needed?

No

Product specific information

Programming

Yes

IMA code (9 characters)

Unlocking

No

Adaption values reset

No



Bleed

No

adjustment at mounting_1

No

adjustment at mounting_2



Tightening torques

Injector/ retaining clamp

15 Nm + 70°

High Pressure pipe nuts

25 Nm

Assembly instructions

Recommendation: replace fuel filter

Replace sealing washer

Recommendation: replace sealing ring

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.

