

Product info sheet

Robert Bosch

0445110325

Special tools needed?

No

Product specific information

Programming

Yes

IMA code (9 characters)

Unlocking

No

Adaption values reset

No

Bleed


No

adjustment at mounting_1

No

adjustment at mounting_2

--



Tightening torques

Injector/ retaining clamp

20 Nm

High Pressure pipe nuts

24 Nm

Assembly instructions

Replace sealing washer

Recommendation: replace fuel filter

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.

