

Product info sheet

Robert Bosch

0445117028

Special tools needed?

Yes

Use special tool to turn the coupling nut.



Product specific information

Programming

Yes

IMA code (7 characters)

Unlocking

No

Adaption values reset

No

Bleed

Yes

Activate feed pump by OBD

adjustment at mounting_1

No

adjustment at mounting_2



Tightening torques

Injector/ retaining clamp

8 Nm + 90°

High Pressure pipe nuts

25 Nm

Assembly instructions

Recommendation: replace fuel filter

Replace sealing washer

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.

