

Product info sheet

Denso

DCRI105130

Special tools needed?

No

Product specific information

Programming

No

Classification by electric resistance

Unlocking

No

Adaption values reset

No

Bleed

No

adjustment at mounting_1

No

adjustment at mounting_2

--



Tightening torques

Injector/ retaining clamp

26 Nm

High Pressure pipe nuts

23 Nm

Banjo fuel fitting

18 Nm

Assembly instructions

Replace sealing washer

Check backleak at -600 mbar

Recommendation: replace gasket fuel connection

Recommendation: replace fuel filter

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.