

febi bilstein – Working well under pressure

Compressed air is vital for all heavy commercial vehicles. Not only is the brake system reliant but also auxiliary equipment such as air suspension, transmission shift or even the horn will not work without it.

There are many reasons for failure of the compressed air system. A common reason is failure of the compressed air line from the compressor shown below. Engine vibrations can cause metal fatigue to the line and as a result the supply of compressed air is compromised. The truck is no longer roadworthy and must be repaired.

febi bilstein offers the right repair solution under the febi no. 44800.

febi no. 44800



to fit:
DAF CF85, XF95, XF105
OE No. 1909 791

The complete range can be found at: www.trucks.febi-parts.com