

# Technical Bulletin

Technical Helpline: +44(0)1622 833004 Fax: +44(0)1622 834004

## Kia Sedona Clutch Kit Replacement

Applications: Kia Sedona 2.9DT 1999>2006

Applicable References: ADG03035 / ADG03058 / ADG03325

Date Issued: 11/2012

We have had reports of clearance and gear selection problems for the Kia Sedona 1999>2006 2.9DT. Repairers understandably assume that the clutch is at fault and fit a new clutch kit; however this does not always rectify the problem.



### ADG03325



We have found that the cause of the problem can lie with a crack in the clutch release fork, as the release fork on this model can fracture and flex during operation and not allow the clutch to fully disengage.

It is highly recommended that the clutch release fork is replaced during the clutch replacement process. Failure to change the fork could cause clearance problems and difficulty in selecting gears. This would not be covered under the Blue Print warranty agreement.

**Disclaimer :** Any technical information is produced in good faith. Blue Print always recommend that vehicle maintenance and diagnostics are only carried out by suitably experienced people using appropriate tools in a safe manner within a workshop environment. Blue Print and their customers cannot be held responsible for the correctness of, or misinterpretation of the above technical information. Images shown are for illustrative purposes only and may not be representative of the products or vehicles described.



[www.blue-print.com](http://www.blue-print.com)